



GENERAL RECOMMENDATIONS NOT PORTRAYED ON MAP (with Problem)
 -Install international signage.
 (Lack of signage.)

Revision: June 2003

FIGURE 2 - CATS RECOMMENDATIONS FOR NYCDOT REPAVING WORK: STREET MARKINGS & SIGNAGE



LEGEND

- Study Area
- Install Mid-Block Crossing Near this Intersection
- Separate EB Traffic into Tunnel/Non-Tunnel Lanes
- + Install High-Visibility Crosswalk Markings
- Install/Improve Directional Signage
- P Install Directional Signage to Parking Facilities

(Callout Box) Problem Identified