




GENERAL RECOMMENDATIONS NOT PORTRAYED ON MAP (with Problem)
 Incorporate trees into sidewalks and future median design where it does not conflict with vendor space
 (Pedestrian space poorly defined.)

Revision: June 2003

FIGURE 3 - CATS RECOMMENDATIONS FOR NYCDOT REPAVING: MAINTENANCE AND OTHER ISSUES



LEGEND

-  Study Area
-  Repair Potholes
-  Implement a Pedestrian Mall
-  Improve Illumination
-  Restore Belgian block pavement

 (Callout Box) Problem Identified